

## **Rebuild Like a Pro**

Maximizing uptime and maintaining a great spray pattern are essential to thriving contractors. By significantly decreasing the labor and troubleshooting time required to keep guns in service, you can now focus on the rest of your business. With ProConnect technology in the Fusion PC gun, the entire fluid section including the side seals and all associated o-rings are replaced in a single cartridge compared to individual parts. This means you can stock fewer parts and have a perfect rebuild in seconds, with a factory tested replacement cartridge.

## **Factory Rebuild with ProConnect Technology**

Troubleshooting a gun in the field can be a difficult task, especially for new applicators, due to the amount of moving parts required to properly spray fast-set two component materials. Having the ability to perform a factory rebuild on the job site with minimal downtime will allow the sprayer to spend more time spraying, maximizing uptime, and getting jobs done faster.

## **Ordering Information**

Fusion PC Guns, Round

25P588 PC42RD (01) mix chamber (0.042 orifice size)

25P589 PC52RD (02) mix chamber (0.052 orifice size)

Fusion PC Gun Retrofit, Round

25P701 PC42RD (01) mix chamber (0.042 orifice size)

25P702 PC52RD (02) mix chamber (0.052 orifice size)

Repair Parts

19Y301 Fusion ProConnect Replacement Cartridge, 3 pack

19Y308 Fusion ProConnect Replacement Cartridge, 5 pack



## Contact us today!

Visit www.graco.com/fusionpc to learn more or have a Graco representative contact you.

